

Current Production and Service Parts should be shipped out with highlighted versions installed.

Year	X30	X35	X40	XD	CL55	Apollo				Bridge			
						CM-40 ECU	EM-24 ECU	Drill Fold ECU	Scale Link	IB-1	IB-2	MDECU	SECU
2013	3.15.206									2.00.07		3.6	1.4.5
2014	3.16.36					2.11-r6,0.0.18	0.0.15			2.07.03		3.6	1.4.5
2015	3.18.513bg					2.12-r8,1.0.2	0.1.6			4.04-r8		3.6	1.4.5
2016	3.18.517bg					2.13-r1,1.0.4	0.1.6			4.04-r10		3.6	1.4.5
2016	* 3.18.518bg					2.13-r1,1.0.4	0.1.6			4.04-r10		3.6	1.4.5
2016	3.20.509					3.09-r2,1.1.4	0.1.2,0.1.2	1.0.9,3.1.2		4.04-r10		3.6	1.4.5
2017	* 3.20.513					3.10-r1,1.1.7	0.2.0,0.2.0	1.0.9,3.1.2		4.04-r10		3.6	1.4.5
2018	3.24.509	* 4.01.509				5.10.02,1.6.1	0.3.1,0.3.1	1.0.9,3.1.2	1.01.07 171110	4.04-r12		3.6	1.4.5
2019		4.02.511				6.07.00,1.6.1	0.3.1,0.3.1	1.0.9,3.1.2	1.01.07 180808	4.04-r12		3.6	1.4.5
2020		* 4.02.511				6.07.00,3.0.13	0.3.1,0.3.1	1.0.9,3.1.2	1.01.11 190625	4.04-r12		3.6	1.4.5
2020	* 3.24.511					5.11.00,3.0.13	0.3.1,0.3.1	**1.0.9,3.1.2		4.04-r12	IB2 4.04.105	3.6	1.4.5
2020		4.04.516			0.8.8.M2M-2	7.08.01,3.0.13	0.3.1,0.3.1	1.0.9,3.1.2	1.01.11 190625	****	****	****	****
2021		* 4.04.521		XD 5.00.41	0.8.8.M2M-2	7.08.07,3.0.13	0.3.1,0.3.1	1.0.9,3.1.2	1.01.11 201015				
2022		* 4.06.05		XD 5.00.41	0.8.8.M2M-2	7.08.08,3.0.15	0.3.1,0.3.1	1.0.9,3.1.2	1.01.11 201015 1.01.11 210915				
2023		X35 5.02.24.21		XD 5.02.24.21	4.1.0/5.1.0	10.05.06,3.3.7	0.4.1,0.4.1	1.0.9,3.1.2	1.01.11 220629				
		X35 5.02.24.31				10.05.07,3.3.7							
		X35 5.02.24.33											
2024		X35 5.02.24.38	X40 5.02.24.38	XD 5.03.34	4.1.0/5.1.0 6.0.2/7.0.2 7.1.0/8.1.0	10.05.07,3.3.7	0.4.1,0.4.1	1.0.9,3.1.2	1.01.11 220629				
		X35 5.03.34.2	X40 5.03.34.2			10.08.04,3.3.7							
		X35 5.03.34.14	X40 5.03.34.14										
2025		* X35 5.25.03	* X40 5.25.03	* XD 5.03.34	7.1.0/8.1.0	10.09.01,3.3.7	0.4.1,0.4.1	1.0.9,3.1.2	*** 1.01.11 240227		IB2 5.01.03	3.6	1.4.5

Revised December 2024

* Recommended versions to use that are available on the Bourgault download site.

** 3.24.511 software doesn't allow the drill fold ECU to be updated. Use 3.20.513 software or an X35 to do the update to the drill fold ECU.

*** Scale Link firmware is compatible with any software version so does not need to be updated along with the monitor. The latest firmware will only be accepted on the newer hardware versions.

**** IB-1 & IB-2 firmware may not sync properly with 4.04.516 or newer V4 software after restarting without swapping profiles, they need to remain on older V4 software.

Series 2 CM-40 ECU's require new Auxiliary firmware which is compatible with 3.24.511/4.02.511 or newer software.

Master file located in: V:\Proto\RD\X35_X40\Software release docs\Software_firmware versions.xls

BiC Related Software

Year	Accuset	BiC
2025	V1.7.XX ^a	25.1.y ^a

Revised December 2024

^a for every version update, EOL document 3163-00-30 must also be updated & sent to vendor. Found in: V:\Proto\RD\Bourgault Implement Control\Documentation\Vendor Documents\3163-00-30