

Year	X30	X35	X40	XD	CL55	Apollo				Bridge			
						CM-40 ECU	EM-24 ECU	Drill Fold ECU	Scale Link	IB-1	IB-2	MDECU	SECU
2013	3.15.206									2.00.07		3.6	1.4.5
2014	3.16.36					2.11-r6,0.0.18	0.0.15			2.07.03		3.6	1.4.5
2015	3.18.513bg					2.12-r8,1.0.2	0.1.6			4.04-r8		3.6	1.4.5
2016	3.18.517bg					2.13-r1,1.0.4	0.1.6			4.04-r10		3.6	1.4.5
2016	* 3.18.518bg					2.13-r1,1.0.4	0.1.6			4.04-r10		3.6	1.4.5
2016	3.20.509					3.09-r2,1.1.4	0.1.2,0.1.2	0.14-r13,1.1.1		4.04-r10		3.6	1.4.5
2017	* 3.20.513					3.10-r1,1.1.7	0.2.0,0.2.0	0.14-r14,1.1.1		4.04-r10		3.6	1.4.5
2018	3.24.509	* 4.01.509				5.10.02,1.6.1	0.3.1,0.3.1	1.0.5,1.1.1	1.01.07 171110	4.04-r12		3.6	1.4.5
2019		4.02.511				6.07.00,1.6.1	0.3.1,0.3.1	1.0.8,1.6.1	1.01.07 180808	4.04-r12		3.6	1.4.5
2020		* 4.02.511				6.07.00,3.0.13	0.3.1,0.3.1	1.0.8,1.6.1	1.01.11 190625	4.04-r12	4.04.105	3.6	1.4.5
2020	* 3.24.511					5.11.00,3.0.13	0.3.1,0.3.1	** 1.0.5,3.1.2		4.04-r12	4.04.105	3.6	1.4.5
2020		4.04.516			0.8.8.M2M-2	7.08.01,3.0.13	0.3.1,0.3.1	1.0.8,3.1.2	1.01.11 190625	****	****	****	****
2021		* 4.04.521		XD 5.00.41	0.8.8.M2M-2	7.08.07,3.0.13	0.3.1,0.3.1	1.0.8,3.1.2	1.01.11 201015				
2022		* 4.06.05		XD 5.00.41	0.8.8.M2M-2	7.08.08,3.0.15	0.3.1,0.3.1	1.0.8,3.1.2	1.01.11 201015 1.01.11 210915				
2023		X35 5.02.24.21 X35 5.02.24.31 X35 5.02.24.33		XD 5.02.24.21	4.1.0/5.1.0	10.05.06,3.3.7 10.05.07,3.3.7 10.05.07,3.3.7	0.4.1,0.4.1	1.0.9,3.1.2	1.01.11 220629				
2024		X35 5.02.24.38 * X35 5.03.34.2	X40 5.02.24.38 * X40 5.03.34.2	* XD 5.03.34	4.1.0/5.1.0 6.0.2/7.0.2 7.1.0/8.1.0	10.05.07,3.3.7 10.08.04,3.3.7	0.4.1,0.4.1	1.0.9,3.1.2	*** 1.01.11 220629				

Revised January 2024

* Recommended versions to use that are available on the Bourgault download site.

** 3.24.511 software doesn't allow the drill fold ECU to be updated. Use 3.20.513 software or an X35 to do the update to the drill fold ECU.

*** Scale Link firmware is compatible with any software version. The latest Scale Link firmware will only be accepted on the newer hardware version.

**** IB-1 & IB-2 firmware may not sync properly with 4.04.516 or newer software after restarting without swapping profiles, they need to remain on older software.

Series 2 CM-40 ECU's require new Auxiliary firmware which is compatible with 3.24.511/4.02.511 or newer software.