

Year	Apollo								Bridge			
	X30	X35	XD	CL55	CM-40 ECU	EM-24 ECU	Drill Fold ECU	Scale Link	IB-1	IB-2	MDECU	SECU
2013	3.15.206								2.00.07		3.6	1.4.5
2014	3.16.36				2.11-r6,0.0.18	0.0.15			2.07.03		3.6	1.4.5
2015	3.18.513bg				2.12-r8,1.0.2	0.1.6			4.04-r8		3.6	1.4.5
2016	3.18.517bg				2.13-r1,1.0.4	0.1.6			4.04-r10		3.6	1.4.5
2016	* 3.18.518bg				2.13-r1,1.0.4	0.1.6			4.04-r10		3.6	1.4.5
2016	3.20.509				3.09-r2,1.1.4	0.1.2,0.1.2	0.14-r13,1.1.1		4.04-r10		3.6	1.4.5
2017	* 3.20.513				3.10-r1,1.1.7	0.2.0,0.2.0	0.14-r14,1.1.1		4.04-r10		3.6	1.4.5
2018	3.24.509	* 4.01.509			5.10.02,1.6.1	0.3.1,0.3.1	1.0.5,1.1.1	1.01.07 171110	4.04-r12		3.6	1.4.5
2019		4.02.511			6.07.00,1.6.1	0.3.1,0.3.1	1.0.8,1.6.1	1.01.07 180808	4.04-r12		3.6	1.4.5
2020		* 4.02.511			6.07.00,3.0.13	0.3.1,0.3.1	1.0.8,1.6.1	1.01.11 190625	4.04-r12		3.6	1.4.5
2020	* 3.24.511				5.11.00,3.0.13	0.3.1,0.3.1	** 1.0.5,3.1.2		4.04-r12	4.04.105	3.6	1.4.5
2020		4.04.516		0.8.8.M2M-2	7.08.01,3.0.13	0.3.1,0.3.1	1.0.8,3.1.2	1.01.11 190625	****	4.04.105	3.6	1.4.5
2021		* 4.04.521	XD 5.00.41	0.8.8.M2M-2	7.08.07,3.0.13	0.3.1,0.3.1	1.0.8,3.1.2	1.01.11 201015		4.04.105	3.6	1.4.5
2022		* 4.06.05	* XD 5.00.41	0.8.8.M2M-2	7.08.08,3.0.15	0.3.1,0.3.1	1.0.8,3.1.2	***1.01.11 201015		4.04.105	3.6	1.4.5

Revised Oct. 2021

* Recommended versions to use that are available on the Bourgault download site.

** 3.24.511 software doesn't allow the drill fold ECU to be updated. Use 3.20.513 software or an X35 to do the update to the drill fold ECU.

*** This latest 1.01.11 201015 Scale Link firmware is bundled with all software downloads as it is compatible with all software versions.

**** 4.04-r12 IB-1 firmware may not sync properly with 4.04.516 or newer software after restarting without swapping profiles.