



X 35 Apollo system



X35 Apollo system

X35 Monitor





X35 Monitor

- Monitor screen is 12.1 inches (diagonal)
- LINUX operating system – not windows
- Can-based communication. No serial ports
- One USB port






Turning On

To turn on the X35 console, press and hold green power button (approximately 3 sec), located on the back of the console.

Note: please follow the shut down procedure and DO NOT hold button until display shuts down.



Shutting Down

To shut down the console, briefly press the green ON/OFF button. The system will ask if you want to power down. Select YES to turn off or No to continue working.

Note all X35's will turn on and off with tractor key.



X35 Apollo system

Light Sensor and Power LED





Console Toolbar

The X35 has some dedicated buttons/controls on the lower console toolbar which is accessed by swiping up from the bottom edge of the screen.



Power down button



Help button



USB Eject



Take Screenshot button



Configure Home screens button



Go to Home Screen button



Decrease and Increase Screen brightness buttons



Toggles screen brightness between day and night modes





Setup

- All configuring and parameter entry is completed in the setup menu
- To toggle between the screens use the wrench ON the guidance screen and the running man on the settings page