



TO: All Bourgault Dealers  
ATTN: Service Manager, Parts Manager, Sales Manager  
SUBJECT: ASC Hydraulic Block Mount - Upgrade

**FIX ON FAILURE** (Failure Code 6.16)

Effective serial number range: ASC units and kits produced prior to August 2015.

**BACKGROUND:**

A running change has been implemented on ASC equipped 7000 series tanks and all ASC kits to eliminate failures of the ASC hydraulic block mount. The new hydraulic mount has been strengthened with the addition of a gusset. This new ASC hydraulic block mount is being made available as an upgrade. Units having experienced failure of this mount, those equipped with tracks, those exposed to higher than average transport distances or those operating in more challenging conditions should be upgraded to prevent this failure.

**CORRECTIVE ACTION:**

- Upgrade the old mounts to the new stronger version

Part Number	Description	Ref price	List Price
6363-04-10	ASC Hydraulic Block Mount		

**WARRANTY DETAIL:**

**CONTACT DEALER FOR PRICING AND WARRANTY DETAILS**

If you have any questions regarding this TSB, please contact your Bourgault Service Representative.

Old Style mount



New style mount  
with added gusset  
part # 6363-04-10

