



TO: All Bourgault Dealers
 ATTN: Service Manager, Parts Manager, Sales Manager
 SUBJECT: X35 Software and Firmware Versions – for spring 2019

FIX ON FAILURE (Failure Code 15.19)

Effective serial number range: Model year 2019 - 7000 series tanks equipped with X35 Apollo.

BACKGROUND:

The final versions of X35 software and firmware to be used in all model year 2019, 7000 series air-seeders has been fully released. As of January 21st all 7000 series tanks (X35’s and ecu’s) and tillage units (ecu’s) will be loaded with this model year 2019 software and firmware.

Bourgault began installing the latest software and firmware immediately upon its final release; however units assembled and shipped to your dealerships prior to Jan 21st will not have these final versions of software or firmware installed.

It is necessary that all model year 2019 seeding systems receive it prior to seeding this spring.

- For 2019 the brake system control has been integrated into the X35
 - without this update the brakes will not function.

Without all matching and compatible versions of software and firmware your 7000 series X35 equipped tank and associated drill WILL NOT function properly.

Below is a list of the required software and firmware versions to be used with all Model year 2019 X35 equipped systems for the spring of 2019.

Component	Latest versions for spring 2019
X35 MONITOR SOFTWARE	4.02.511
CM-40 - firmware	6.07.00 1.6.1
EM-24 - firmware	0.3.1 0.3.1
SCALE LINK - firmware	1.01.07 180808
DRILL FOLD ECU - firmware	1.08 1.6.1



X35
Apollo

Contact your dealership for more details and to confirm your model year 2019 seeding system is loaded with the proper software and firmware versions.